

**To:** Saari, Christopher A - DNR  
(Christopher.Saari@Wisconsin.gov)[Christopher.Saari@Wisconsin.gov]; Egan,  
Robert[egan.robert@epa.gov]; KHanson@ldftribe.com[KHanson@ldftribe.com]  
**From:** Dave Larsen  
**Sent:** Thur 7/14/2016 2:14:27 AM  
**Subject:** FW: Attached Image  
2655\_001.pdf


Well construction logs in area. Below data was pulled from 1<sup>st</sup> investigation. I was not able to locate well log for old restaurant. I will continue searching...

<u>Well Location</u>	<u>Casing Depth</u>	<u>Pumping Rate</u>	<u>Pumping Time</u>	<u>Drawdown</u>
Haskell Lake Road	56 Feet	15 gpm	1 Hour	10 Feet
Restaurant	75 Feet	5 gpm	unknown	significant
Motel Well #2	31 Feet	20 gpm	3 Hours	7 Feet
Motel Well #3	75 Feet	15 gpm	6 Hours	None
Motel Well #4	38 Feet	15 gpm	72 Hours	9 Feet
Kozak Well	75 Feet	20 gpm	unknown	unknown

Thank you,

David N. Larsen P.G




Hydrogeologist / Professional Geologist



**David N. Larsen, P.G.**  
Hydrogeologist  
Dlarsen@REIengineering.com

Tel: 877-734-7745  
715-675-9784  
Cell: 715-551-3434  
Fax: 715-675-4060



Connect with us :   

*Confidentiality Notice: This message is intended for the recipient only. If you have received this e-mail in error please disregard.*

**From:** noreply  
**Sent:** Wednesday, July 13, 2016 9:31 PM  
**To:** Dave Larsen <dlarsen@reiengineering.com>  
**Subject:** Attached Image